



SOUTH EAST FOREST RESCUE

<http://www.myspace.com/southeastforestrescue>

PO BOX 899 Moruya, NSW, 2537

sefr@fastmail.fm

DECCW Enviroline
Environment Protection and Regulation Group
Department of Environment, Climate Change and Water.

6 March 2011

Re: EPL & TSL breaches in Badja State Forest

Dear DECCW,

Following our recent inspection of Badja State Forest we wish to report some noteworthy findings. GPS setting used is WGS84.

Along Badja Forest Road at GPS point 0725363/5994604 we believe that there has been logging in what should have been marked as a Rocky Outcrop.

On old Falcon Road at point 0731304/6000838 there has been a partial collapse of the bridge with ensuing road material falling into the creek.

From the bush milling point down the end of Balook Road at 0729536/5998434 there is the track leading into recent logging of compartment 2029/1. The use of machinery in this area has led to significant rutting along the various tracks used during the operation.

In compartment 2044 at point 0731811/6001512 we believe to have found another Rocky Outcrop that had been logged.

We believe that a DECCW field audit would be productive and uncover further non-compliance with prescriptions.

Kind Regards

L Stone